Machine: 500T Press				
		Int. or Ext.		-
No	Description of Operation	Time	Cycle Time	
	Scaling Line			00:06:03
1	Open Door	I		00:00:06
2	Spray die	I		00:00:00
3	close door and close die	I		00:00:24
4	climb up	I		00:00:12
5		Ī		00:00:12
	fit hanging strap	-		
7	drop crane	I		00:00:20 00:00:52
	attach crane to die	1		
8	climb down	- 1		00:00:02
9	walk to rear	I		00:00:11
10	switch off manifolds	I		00:00:25
11	remove pipes from fixed die	I		00:00:22
12	remove pipes from moving die	I		00:00:14
13	undo m.p. clamps at rear x2	I		00:01:04
14	undo f.p. clamps at rear x2	I		00:00:50
15	walk to front	I		00:00:29
16	open door	I		00:00:07
17	remove pipes from front	I		00:00:33
18	undo m.p. clamp	I		00:00:41
19	undo f.p. clamps at front x2	I		00:00:25
20	die out and lifted	I		00:00:31
21	move die to pallet	i		00:01:20
22	unhook crane from die	i		00:00:08
		Ī		00:00:08
23	move crane to new die	I		
	attach crane to die			00:00:18
25	return to machine	I		00:00:16
26	withdraw barrel	I		00:00:24
27	open guard	I		00:00:04
28	clean area out	I		00:00:24
29	remove adapter	I		00:00:10
30	remove clamps from platten	I		00:02:03
31	new die moved to machine	I		00:01:42
32	replace clamps on f.p. X2	I		00:02:01
33	Adjust m.p. clamps & reposition	1		00:01:37
34	Walk to rear	I		00:00:14
35	replace clamps on f.p. X2	i		00:02:17
36	Adjust m.p. clamps & reposition	i		00:01:37
37	Walk to front	I		00:00:11
38		I		00:00:11
39	climb onto machine			
	undo crane from die, climb down	I		00:00:20
40	fit ejector bars to machine	I		00:00:40
41	tighten ejector bars	I		00:06:03
42	pipes fitted f.p. x4	I		00:01:10
43	pipes fitted m.p. x3	I		00:00:26
44	Walk to rear	I		00:00:14
45	pipes fitted on both die halves	I		00:04:24
46	manifold taps on	I		00:00:25
47	Walk to front	I		00:00:14
48	close dies	I	<u> </u>	00:00:03
49	check dies	I		00:00:50
50	open dies	I		00:00:29
51	Spray die	i		00:00:15
52	close door	I		00:00:07
53	close dies	Ī		00:00:04
54		1		00:00:04
55	1st part out	-		00:00:59
	2nd shot out	I		
56	3rd shot out - adjust heat, speed	I		00:01:08
57	4th shot out	I		00:01:07
58	5th shot out - increase speed	I		00:01:16
59	6th shot out	I		00:01:01 0:46:17